



07-17-03

Further to the mandatory service bulletin number CW03-01 issued by Capewell Components. <http://www.capewell.com>

This test is mandatory on all Javelin / Odyssey harness container systems manufactured January 2002 through July 2003. This information can be found on the T.S.O. label. This includes all reserve ripcords manufactured as spare or replacement parts during this time period as well. This date information will be stamped SP02 or SP03 on the hard handles. For soft reserve ripcords any batch number greater than 12018.

If you have any questions you can do so by contacting James G Haggas (aggie) by e-mail at aggie@sunpath.com