

SERVICE

BULLETIN (REVISION B)

DATE:	May 01, 2000	# of Pages: 4
REFERENCE:	SERVICE BULLETIN # SPSB: 03032000 – Revision B	
SUBJECT:	MAIN CLOSING LOOP RETAINER – Grommet Protection	
STATUS:	MANDATORY for Javelin's manufactured prior to September 1993, RECOMMENDED for Javelin's manufactured September 1993 up to and including March 2000.	

IDENTIFICATION:

Javelin Harness/Container Assemblies: **Javelins Manufactured Prior to and including March 2000.**

BACKGROUND:

Small diameter main canopy suspension lines (similar to Microline 550 and Vectran 500) can get caught around the grommet in the main Closing Loop Retainer and could result in a serious horseshoe malfunction with a suspension or steering line caught in the container after deployment.

SERVICE BULLETIN REVISION A: Rescinded April 19, 2000.

SERVICE BULLETIN REVISION B:

Before Next Jump - The **mandated** field repair for **Javelins manufactured prior to September 1993**, (as addressed in Service Bulletin # SPSB 03032000) must be done by a suitably qualified rigger.

At Next Reserve Repack - The **mandatory** modification for the Closing Loop Retainer affecting **Javelin's manufactured prior to September 1993**, must be done by a suitably qualified rigger. See attached instructions.

MINIMUM TOOLS REQUIRED:

Sewing machine (capable of both straight and zig-zag stitching), Unpicker, Scissors, Nylon E-Thread, Marking Pencil.

COMPLIANCE:

Before Next Jump:

Service Bulletin # SPSB 03032000 **Mandatory for Javelins manufactured prior to September 1993.**

At the next reserve repack:

- | | |
|--------------------------------------|---|
| 1. # SPSB 03032000 Revision B | Mandatory for Javelins manufactured prior to September 1993. |
| 2. # SPSB 03032000 Revision B | Recommended for Javelins manufactured September 1993 up to and including March 2000. |

Note compliance with this Service Bulletin on Packing Data Card.

AUTHORITY:

Derek Thomas, President
Sun Path Products, Inc.
4439 Skydive Lane, Zephyrhills, FL 33540, USA.
Telephone: (813) 782-9242, Fax: (813) 788-3057
E-mail: info@sunpath.com

DISTRIBUTION:

- | | |
|---|--|
| 1. Sun Path Products, Inc. Website www.sunpath.com | 2. All Sun Path Products, Inc. Dealers. |
| 3. PIA Technical and Rigging Committee. | 4. IPC Technical Committee |
| 5. FAA ORL MIDO | 6. FAA Engineering Atlanta |
| 7. All Parachuting Publications. | 8. National Aero Clubs, Parachuting Section. |
| 9. Military Parachute Organizations. | |